
## **OVERMOLDING ULTIMATE UP01**





SIZE	ØD	L1	L2	Ød
07	9.9	22.2	1.5	4.8
08	8.5	27.5	1.5	5.2
11	13	26.8	1.5	7.8
13	16	35.8	2.0	9.8
15	18	35.8	2.0	11.3
18	20	40.6	2.0	14.8

∅d = Cable max outer diameter


All dimensions in mm	Rev.	Pages	Notes :
600608	2	1/2	



Information provided herein is believed to be accurate at time of publishing. Fischer Connectors reserves the right to make modifications on products for continuous improvement without prior notice.

## OVERMOLDING ULTIMATE UR50





SIZE	ØD	L1	L2	Ød
07	9.9	21.2	1.5	4.8
08	8.5	27.2	1.5	5.2
11	13	26.5	1.5	7.8
13	16	36.3	2.0	9.8

Ød = Cable max outer diameter

All dimensions in mm	Rev.	Pages	Notes
600608	2	2/2	



Information provided herein is believed to be accurate at time of publishing. Fischer Connectors reserves the right to make modifications on products for continuous improvement without prior notice.